

Inspection Photos
Location Name: H. Stewart 2
Location ID: 312804



Photo 1. Overview of location taken facing west. Stained snow visible on right side of wellhead.

