



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Dec 30, 2019 8:58:45 AM MST
Server Receive Date:	Dec 30, 2019 9:20:52 AM MST
Reference Number:	20191230-18128132991
Location:	15731 US-550, Bloomfield, NM 87413, USA Dec 30, 2019 8:57:11 AM MST [View Map]

Information

Name	l.guerrero@kosinm.com
Date	Dec 27, 2019
Well Name	SO UTE 33-10;15- 3
API Number	50670883300
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down

Photo of first corrective action completed



Completed work description Corrective Action 1

Back filled erosional tunnel.

Photo of second corrective action completed



Completed work description of corrective action 2
Photo of third corrective action completed



Installed silt trap and rock armored run down.

Completed work description of corrective action 3
Photo of fourth corrective action completed



Completed work description of corrective action 4
Summary of all work completed

Back filled erosional tunnel. Installed silt trap with
rock armored run down