



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Dec 31, 2019 2:25:45 PM MST
Server Receive Date:	Dec 31, 2019 2:25:54 PM MST
Reference Number:	20191231-18128277172
Location:	5 Rd 2300, Aztec, NM 87410, USA Dec 31, 2019 2:20:43 PM MST [ <a href="#">View Map</a> ]

## Information

Name	l.guerrero@kosinm.com
Date	Dec 23, 2019
Well Name	PINE RIVER 04-32 1
API Number	50670648200
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down

Photo of first corrective action completed



Completed work description Corrective Action 1

Rock armored erosion channel.

Photo of second corrective action completed



Completed work description of corrective action 2  
Photo of third corrective action completed



Completed work description of corrective action 3  
Photo of fourth corrective action completed



Completed work description of corrective action 4  
Summary of all work completed

Removed stained soils.

Installed silt bowls with rock armored run downs and  
cleaned up stained soils.