



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Dec 31, 2019 2:39:13 PM MST
Server Receive Date:	Dec 31, 2019 2:39:20 PM MST
Reference Number:	20191231-18128277336
Location:	5 Rd 2300, Aztec, NM 87410, USA Dec 31, 2019 2:39:00 PM MST [View Map]

Information

Name	l.guerrero@kosinm.com
Date	Dec 12, 2019
Well Name	JONES GAS UNIT 34-16 1
Location Name (Other)	Jones 34-16 3
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down

Photo of first corrective action completed



Completed work description Corrective Action 1

Rock armored erosion channel.

Photo of second corrective action completed



Completed work description of corrective action 2
Completed work description of corrective action 3
Completed work description of corrective action 4
Summary of all work completed

.
.
.

Installed storm water control by rock armoring
erosion channel.