



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Jan 6, 2020 1:06:00 PM MST
Server Receive Date:	Jan 6, 2020 1:08:27 PM MST
Reference Number:	20200106-18128757647
Location:	8344 CO-151, Ignacio, CO 81137, USA Jan 6, 2020 1:07:57 PM MST [ <a href="#">View Map</a> ]

## Information

Name	colen@horizonenvservices.com
Date	Jan 6, 2020
Location Name (Other)	Marquez A 2, Luchini 32-6-12 2
Location API (Other)	0500706327
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

Cut and removed Canada thistle from East side

Photo of second corrective action completed



Completed work description of corrective action 2

Cut and removed Canada thistle from South side

Photo of third corrective action completed



Completed work description of corrective action 3  
 Photo of fourth corrective action completed



Completed work description of corrective action 4  
 Additional photos



Summary of all work completed

Cut and removed Canada thistle from West side

Cut and removed Canada thistle from North side

Cut and removed Canada thistle from all sides of project area