



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Jan 6, 2020 2:27:59 PM MST
Server Receive Date:	Jan 6, 2020 2:30:32 PM MST
Reference Number:	20200106-18128772002
Location:	8344 CO-151, Ignacio, CO 81137, USA Jan 6, 2020 2:27:38 PM MST [View Map]

Information

Name	colen@horizonenvservices.com
Date	Jan 6, 2020
Well Name	TAICHERT GAS UNIT 31-01 4
Location Name (Other)	TAICHERT 31-01 2
API Number	50670993800
Location API (Other)	50670993900
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

Cut and removed musk thistle, russian knapweed and Canada thistle on North side

Photo of second corrective action completed



Completed work description of corrective action 2

Cut and removed musk thistle, ruassian knapweed and Canada thistle on East side

Photo of third corrective action completed



Completed work description of corrective action 3

Cut and removed and Canada thistle on South side

Photo of fourth corrective action completed



Completed work description of corrective action 4

Cut and removed musk thistle on West side

Additional photos



Summary of all work completed

Cut and removed noxious weeds from all sides of project area. Russian knapweed along access road will be treated again.