

**FORM
43**Rev
02/17**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109**OGCC RECEPTION****Receive Date:****12/06/2019****Document Number:****402256008****ANALYTICAL SAMPLE DATA SUBMITTAL FORM****Uses of Ground Water Sampling Form**

Submitt a New Water Quality Sample Location to the COGCC for rules 317B, 318A.5, 608, 609.d(3)., Condition of approval, or other reason.

Submitt a New Water Quality Sample to the COGCC for rules 317B, 318A.5, 608, 609.d(3)., Condition of approval, or other reason.

Operator Information

OGCC Operator Number: 47120 Contact Person: Jacob Rupert
Company Name: KERR MCGEE OIL & GAS ONSHORE LP Phone: (405) 9908995
Address: P O BOX 173779 Fax: ()
City: DENVER State: CO Zip: 80217-3779 Email: Jacob_Rupert@oxy.com

Well/Facility Information

API Number: 05 - 123-27397 OGCC Facility ID: 287160
Well/Facility Name: CUMMINGS Well/Facility Number: 19-23
Location QtrQtr: SWNW Section: 19 Township: 5N Range: SWNW Meridian: 6
County: WELD Field Name: _____
Federal, Indian or State Lease Number: _____

Information Submitted By:

Company Name: Absaroka Energy and Environmental Solutions Agent Name: Max Moran Title: Env. Professional
Phone Number: 7203525326 Email: max.moran@absarokasolutions.com

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 287160 Facility Name: CUMMINGS 19-23 Facility Type: WELL
Location: QtrQtr: SWNW Sec: 19 Twp: 5N Range: 67W Meridian: 6
County Name: WELD Latitude: 40.387560 Longitude: -104.942290

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 76341 Document Name: Size of file in bytes: 35840 File Name: 2019_09_11_BW_05_123_27397_BHD_Trip_Blank_SGS_COGCC.xls
SampleType: _____ Matrix: _____
Facility ID: 287160 Sample ID: 611797 Sample Name: BW_05_123_27397_BHD_Trip_Blank Sample Date: 09/11/2019
Collection Point: TB Matrix: WATER Pre Post: Trip Blank
Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____
Inspection Number: _____ Spill Number: _____ Laboratory: Accutest Lab Sample ID: DA20181-1

Batch ID: 76339 Document Name: Size of file in bytes: 34816 File Name: 2019_09_11_SP_05_123_27397_C_Isotech_NG4_COGCC.xls
SampleType: _____ Matrix: _____
Facility ID: 287160 Sample ID: 611795 Sample Name: SP_05_123_27397_C Sample Date: 09/11/2019
Collection Point: PRDC Matrix: GAS Pre Post: Production Gas Sample
Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____
Inspection Number: _____ Spill Number: _____ Laboratory: ISOTECH Lab Sample ID: 734122

Batch ID: 76342		Document Name: Size of file in bytes: 36352		File Name: 2019_09_11_BW_05_123_27397_BHD_SGS_COG CC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 287160	Sample ID: 611798	Sample Name: BW_05_123_27397_BHD		Sample Date: 09/11/2019	
Collection Point: BDH	Matrix: WATER	Pre Post: Bradenhead Water Sample			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA20180-1		

Batch ID: 76343		Document Name: Size of file in bytes: 36352		File Name: 2019_09_11_BW_05_123_27397_BHD_Isotech_NG 4_COGCC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 287160	Sample ID: 611800	Sample Name: BW_05_123_27397_BHD		Sample Date: 09/11/2019	
Collection Point: BDH	Matrix: WATER	Pre Post: Bradenhead Water Sample			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 734097		

Batch ID: 76343		Document Name: Size of file in bytes: 36352		File Name: 2019_09_11_BW_05_123_27397_BHD_Isotech_NG 4_COGCC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 287160	Sample ID: 611799	Sample Name: BW_05_123_27397_BHD		Sample Date: 09/11/2019	
Collection Point: BDH	Matrix: WATER	Pre Post: Bradenhead Water Sample			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 734097		

Sample Facility Attachment:

No Facility Attachment

Sample COGCC Well Related:

No Sample COGCC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	The data submitted by the operator can be accessed through the COGIS data system.	01/07/2020
Total: 1 comment(s)		