

Inspection Photos
Operator: BP America
Location/API #: 067-08733
Date: 1-6-2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Although snow covered, revegetation appears to be progressing with perennial grasses such as intermediate wheatgrass and smooth brome within the interim reclamation areas.



Photo 3. View of Canada thistles (approximately 200) observed within the eastern project area.



Photo 4. View of kochia debris within the northern project area.



Photo 5. View of reference area, comprised of open grass field with perennial grasses such as smooth brome.