

Inspection Photos
Operator: BP America
Location/API #: 067-06767
Date: 1-6-2020



Photo 1. View of the project area from the southeastern corner on center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Although snow covered, revegetation appears to be progressing with perennial grasses such as smooth brome within the interim reclamation areas.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of weeds and vegetation around fired equipment.



Photo 5. View of reference area, comprised of open grass field with perennial grasses such as smooth brome.