

Inspection Photos
Operator: BP America
Location/API #: 067-06977
Date: 1-6-2020



Photo 1. View of the project area from the southeastern corner on center.



Photo 2. View of the project area from the from the northwestern corner facing southward. Revegetation appears to be progressing with grasses such as smooth brome and sand dropseed, as well as shrubs such as rubber rabbitbrush.



Photo 3. View of Russian knapweeds observed within the eastern project area.



Photo 4. View of reference area, comprised of open grass field with perennial grasses such as smooth brome.