

Pit Status Evaluation Form

Pit Overview:

Pit Name: STONEHOCKER	Facility ID: 114289
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: BLACK HILLS EXPLORATION AND PRODUCTION INC / 95715	
Updated Operator:	
Form 15 Pit Permit Doc #:	Permit Date:
Related Facilities: STONEHOCKER #8-5 (API 05-001-08693, Facility ID 203193, Loc ID 320241)	

County: ADAMS			
Township: 1S	Range: 67W	Section: 8	QQ: CNE
Original Latitude/ Longitude: 39.982739 / -104.907992			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|-----------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 698446 | Date: 2/8/1989 |
| | Doc #: 320705 | Date: 6/10/1998 |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2314539 | Date: 6/7/1996 |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

No evidence of a pit on location

Pit Status Review Summary:

Based on records review there is no evidence that there was a pit on location; field inspections and pit inventory report documents a concrete produced water vault on location. Battery appears to have been relocated ~2010. Pit status has been changed to Closed.

