

Inspection Photos

API#045-06870

Operator: OXY USA WTP

Inspection Number: 692401536

Inspection Date: 10/25/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources




Photo#1:
Overview of Location from Entry.

October 25, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: OXY PA Cascade Creek API#045-06870



Photo#2:
View of heavily grazed portion of Location.

October 25, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: OXY PA Cascade Creek API#045-06870



Photo#3:
View North of area with ruderal weed population.

Photo#4:
View South of area with ruderal weed population.

October 25, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: OXY PA Cascade Creek API#045-06870