

Inspection Photos
Location Name: Beisel #1
Location ID:319877



Photo#1 Production tank and Produced Water Tank



Photo#2 Separator/ECD/Gas Meter



Inspection Photos
Location Name: Beisel #1
Location ID:319877



Photo#3 Wellhead

Inspection Photos
Location Name: Beisel #1
Location ID:319877



Photo#4 **Bullplug missing**



Photo#5 **Stained Soil**