

Inspection Photos

API: 05-071-07742

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/6/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-07742 | Date: 1/6/2020

Inspection Photos



Photo 1. Facing south toward the access road which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 05-071-07742 | Date: 1/6/2020

Inspection Photos



Photo 2. Facing south toward the location. The equipment has been removed however final reclamation has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07742 | Date: 1/6/2020

Inspection Photos



Photo 3. The electric powerline remain to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07742 | Date: 1/6/2020

Inspection Photos



Photo 4. The powerline cable has not been removed. The wires are unsecured which is a safety concern



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 05-071-07742 | Date: 1/6/2020

Inspection Photos



Photo 5. Facing northwest toward the location which has not been recontoured.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 05-071-07742 | Date: 1/6/2020

Inspection Photos



Photo 6. Facing southeast toward the location standing above the cut slope.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 05-071-07742 | Date: 1/6/2020