

Inspection Photos  
Location Name: SRC Gies Pad  
Location ID: 438495



Photo 1: Tank Battery Sign



Photo 2: Tank Battery

Inspection Photos  
Location Name: SRC Gies Pad  
Location ID: 438495



Photo 3: No BBLS labeling on H2O tanks



Photo 4: Wellhead Sign

**Inspection Photos**  
**Location Name: SRC Gies Pad**  
**Location ID: 438495**



**Photo 5: Wellhead**




**Photo 6: UNSUED EQUIPMENT**

Inspection Photos  
Location Name: SRC Gies Pad  
Location ID: 438495



**Photo 7: Wellhead Sign**



**Photo 8: Wellhead; UNUSED EQUIPMENT**

Inspection Photos  
Location Name: SRC Gies Pad  
Location ID: 438495



Photo 9: Wellhead Sign



Photo 10: Wellhead

Inspection Photos  
Location Name: SRC Gies Pad  
Location ID: 438495



Colorado Oil and Gas Conservation Commission  
40.56735, -104.64364, 1458.4m, 124°  
Jan 7, 2020 15:10:35

Photo 11: Wellhead Sign



Colorado Oil and Gas Conservation Commission  
40.56738, -104.64365, 1459.8m, 127°  
Jan 7, 2020 15:10:40

Photo 12: Wellhead

Inspection Photos  
Location Name: SRC Gies Pad  
Location ID: 438495



Photo 13: Wellhead Sign



Photo 14: Wellhead

Inspection Photos  
Location Name: SRC Gies Pad  
Location ID: 438495



Photo 15: Wellhead Sign



Photo 16: Wellhead

Inspection Photos  
Location Name: SRC Gies Pad  
Location ID: 438495



Photo 17: Wellhead Sign



Photo 18: Wellhead; **UNUSED EQUIPMENT**