

Inspection Photos

API: 05-071-09372

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/6/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-09372 | Date: 1/6/2020

Inspection Photos



Photo 1. Well sign is posted at the meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09372 | Date: 1/6/2020

Inspection Photos



Photo 2. Well is Shit In. Equipment removed at well head.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09372 | Date: 1/6/2020

Inspection Photos



Photo 3. Sign indicates pit closure In Process. Pit liner is in disrepair. This was also identified in the previous inspection.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 05-071-09372 | Date: 1/6/2020

Inspection Photos



Photo 4. Facing east toward the pit. The pit is not in use and should be closed and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09372 | Date: 1/6/2020