

## Inspection Photos

Location Name: UPTOWN FEDERAL 22-27

API#: 05-071-06725

INSP. #: 695101944



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN



## Inspection Photos

Location Name: UPTOWN FEDERAL 22-27 CA DATE 2-2-2020

API#: 05-071-06725

INSP. #: 695101944



**PHOTO 3: IT APPEARS THAT BURN IN FRONT OF TANK HAS BEEN RAN OVER SEVERAL TIMES AND IS NO LONGER ADEQUATE. Repair or install berms or other secondary containment devices per Rule 605.a.(4). CA DATE 2/2/2020.**



**PHOTO 4: NO NFPA STICKER POSTED ON TANK. TANK CAPACITY NOT POSTED ON TANK. INSTALL SIGN TO COMPLY WITH RULE 210.d. CA DATE 2/2/2020.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources