

# Inspection Photos

1/06/2020

Operator: DIAMOND BACK DRILLING &  
SUPPLY INC - 24120

Location ID: 398175

Rio Blanco County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: DIAMOND BACK DRILLING & SUPPLY INC - 24120

Location ID: 398175



**Photo 1:** Photo taken from the south end of the Location, facing west. Photos 1-4 provide an overview of the Location from west, northwest, northeast to east. Location currently covered in snow preventing Reclamation Specialist from conducting an accurate assessment of the reclamation. Follow-up inspection will be needed in a future growing season.



**Photo 2:** See comments under photo 1.

## Inspection Photos

Operator Name: DIAMOND BACK DRILLING & SUPPLY INC - 24120

Location ID: 398175



**Photo 3:** See comments under photo 1.



**Photo 4:** See comments under photo 1.



## Inspection Photos

Operator Name: DIAMOND BACK DRILLING & SUPPLY INC - 24120

Location ID: 398175



**Photo 5:** Photo taken from the location. Photo shows pipe remaining on the Location.