

# Inspection Photos

1/06/2020

Operator: D & D RESOURCES INC - 22315

Location ID: 398078

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: D & D RESOURCES INC - 22315  
Location ID: 398078



**Photo 1:** Photo taken from the west end of the Location, facing east. Photo shows an overview of the Location, including the well marker, and utility pole cut and left on Location.



**Photo 2:** Photo taken from the southwest end of the Location. Photo shows utility pole appears to have been cut down and left on the Location.

Inspection Photos  
Operator Name: D & D RESOURCES INC - 22315  
Location ID: 398078



**Photo 3:** Continued from photo 2: Photo shows anchor associated with the utility pole left on location.



**Photo 4:** Photo taken from the east end of the Location, facing west.