

Inspection Photos

1/06/2020

Operator: D & D RESOURCES INC - 22315

Location ID: 315573

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: D & D RESOURCES INC - 22315
Location ID: 315573



Photo 1: Photo taken from the south end of the Location, facing north. Photo shows overview of the Location and well marker. Photo shows an open pit on the south end of the location (yellow arrow) and the well marker. Photo also stormwater erosion degradation on Location (red arrow).



Photo 2: Photo taken from the south end of the Location, facing northeast. See comments under photo 1.

Inspection Photos

Operator Name: D & D RESOURCES INC - 22315

Location ID: 315573



Photo 3: Photo of well marker and open pit on the south end of the Location



Photo 4: Photo taken from the north end of the Location. Photo shows erosion degradation observed on the cut slopes.