

# Inspection Photos

1/06/2020

Operator: DIAMOND BACK DRILLING &

SUPPLY INC - 24120

Location ID: 398077

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: DIAMOND BACK DRILLING & SUPPLY INC - 24120

Location ID: 398077



**Photo 1:** Photo taken from the south end of the Location, facing north. Photo shows overview of the Location. Photo also shows an open pit on the north end of the location (yellow arrow) and the well marker.



**Photo 2:** Photo taken from the south end of the Location, facing northeast. Photo shows overview of the Location. Photo also shows an open pit on the north end of the location (yellow arrow), and the excavated soils (red arrow).

## Inspection Photos

Operator Name: DIAMOND BACK DRILLING & SUPPLY INC - 24120

Location ID: 398077



**Photo 3:** Photo of well marker and open pit (background).



**Photo 4:** Photo taken from the south end of the location, facing east. Photo shows an open pit on the north end of the location (yellow arrow), and the excavated soils (red arrow).