

# Inspection Photos

Location ID, Name: 328752 HSR-LEBERMAN-63N67W 1SESE



COGCC Field Inspection  
40.24989, -104.83348, 4721.1ft, 154  
01/08/2020 13:13:0

Photo 1 **05-123-16383**  
**HSR-LEBERMAN 16-1**



COGCC Field Inspection  
40.24974, -104.83456, 4727.7ft, 125  
01/08/2020 13:09:4

Photo 2 **Battery**



COGCC Field Inspection  
40.24979, -104.83423, 4717.8ft, 16  
01/08/2020 13:07:3

Photo 3 **Production Equipment**

