

Inspection Photos
Location Name: Clark 22-27
Location ID: 305292




Photo 1: Wellhead Sign



Photo 2: Wellhead; appears weeds have been removed
(Snow covering area)