

Inspection Photos  
Location Name: Booth USX EE 35-17  
Location ID: 306465




Photo 1: Wellhead Sign



Photo 2: Wellhead; appears weeds are removed (snow covering area)