

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/08/2020

Submitted Date:

01/08/2020

Document Number:

694901065

### FIELD INSPECTION FORM

Loc ID 334614 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                                     | Comment |
|--------------|-------|---|---------|
| , Caerus     |       | COGCC.inspections@caerus<br>oilandgas.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 271593      | WELL | PR     | 08/17/2004  | GW         | 045-09905 | GMR 34-7(J34NW)   | PR          |
| 271594      | WELL | PR     | 08/02/2004  | GW         | 045-09907 | GMR 34-10(J34NW)  | PR          |
| 271595      | WELL | PR     | 08/02/2004  | GW         | 045-09908 | GMR 34-15(134NW)  | PR          |
| 271596      | WELL | PR     | 08/14/2004  | GW         | 045-09909 | GMR 34-7C(J34NW)  | PR          |
| 271598      | WELL | PR     | 08/02/2004  | GW         | 045-09910 | GMR 34-15B(J34NW) | PR          |

**General Comment:****COGCC Inspection Report Summary**

On Wednesday 1/8/20 at approximately 1:30 PM, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus J34NW, at Location # 334614 in Garfield County, Colorado.

While there, I observed normal production operations.

This is a summary of inspection report.

| Location   |                           |        |                 |
|--|---------------------------|--------|-----------------|
| <b>Lease Road:</b>                                     |                           |        |                 |
| Type   | Access                    |        |                 |
| comment:   |                           |        |                 |
| Corrective Action:                                     |                           |        | Date:           |
| Overall Good: <input checked="" type="checkbox"/>      |                           |        |                 |
| <b>Signs/Marker:</b>                                   |                           |        |                 |
| Type   | BATTERY                   |        |                 |
| Comment:   |                           |        |                 |
| Corrective Action:                                     |                           |        | Date:           |
| Type   | WELLHEAD                  |        |                 |
| Comment:   |                           |        |                 |
| Corrective Action:                                     |                           |        | Date:           |
| Type   | TANK LABELS/PLACARDS      |        |                 |
| Comment:   |                           |        |                 |
| Corrective Action:                                     |                           |        | Date:           |
| Emergency Contact Number:                              |                           |        |                 |
| Comment:   | 911                       |        |                 |
| Corrective Action:                                     |                           |        | Date: _____     |
| <b>Good Housekeeping:</b>                              |                           |        |                 |
| Type   | DEBRIS                    |        |                 |
| Comment:   |                           |        |                 |
| Corrective Action:                                     |                           |        | Date:           |
| Overall Good: <input checked="" type="checkbox"/>      |                           |        |                 |
| <b>Spills:</b>   |                           |        |                 |
| Type   | Area                      | Volume |                 |
| In Containment: No                                     |                           |        |                 |
| Comment:   |                           |        |                 |
| <input type="checkbox"/> Multiple Spills and Releases? |                           |        |                 |
| <b>Equipment:</b>                                      |                           |        |                 |
| Type:  | Vertical Heated Separator | # 5    | corrective date |
| Comment:   |                           |        |                 |
| Corrective Action:                                     |                           |        | Date:           |
| Type:  | Bird Protectors           | # 1    |                 |
| Comment:   |                           |        |                 |
| Corrective Action:                                     |                           |        | Date:           |
| Type:  | Gas Meter Run             | # 1    |                 |
| Comment:   |                           |        |                 |
| Corrective Action:                                     |                           |        | Date:           |

|                    |     |       |
|--------------------|-----|-------|
| Type: Plunger Lift | # 5 |       |
| Comment:           |     |       |
| Corrective Action: |     | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE         | 1 | 500 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
|                    |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    |       |
|                    |    | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: |       |
|                    | Date: |

| Inspected Facilities  |                  |       |             |             |                  |         |           |               |           |
|-----------------------|------------------|-------|-------------|-------------|------------------|---------|-----------|---------------|-----------|
| Facility ID:          | <u>271593</u>    | Type: | <u>WELL</u> | API Number: | <u>045-09905</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| <b>Producing Well</b> |                  |       |             |             |                  |         |           |               |           |
| Comment:              | <u>producing</u> |       |             |             |                  |         |           |               |           |
| Corrective Action:    |                  |       |             |             | Date:            |         |           |               |           |
| Facility ID:          | <u>271594</u>    | Type: | <u>WELL</u> | API Number: | <u>045-09907</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| <b>Producing Well</b> |                  |       |             |             |                  |         |           |               |           |
| Comment:              | <u>producing</u> |       |             |             |                  |         |           |               |           |
| Corrective Action:    |                  |       |             |             | Date:            |         |           |               |           |
| Facility ID:          | <u>271595</u>    | Type: | <u>WELL</u> | API Number: | <u>045-09908</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| <b>Producing Well</b> |                  |       |             |             |                  |         |           |               |           |
| Comment:              | <u>producing</u> |       |             |             |                  |         |           |               |           |
| Corrective Action:    |                  |       |             |             | Date:            |         |           |               |           |
| Facility ID:          | <u>271596</u>    | Type: | <u>WELL</u> | API Number: | <u>045-09909</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| <b>Producing Well</b> |                  |       |             |             |                  |         |           |               |           |
| Comment:              | <u>producing</u> |       |             |             |                  |         |           |               |           |
| Corrective Action:    |                  |       |             |             | Date:            |         |           |               |           |
| Facility ID:          | <u>271598</u>    | Type: | <u>WELL</u> | API Number: | <u>045-09910</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| <b>Producing Well</b> |                  |       |             |             |                  |         |           |               |           |
| Comment:              | <u>producing</u> |       |             |             |                  |         |           |               |           |
| Corrective Action:    |                  |       |             |             | Date:            |         |           |               |           |

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            |                 | Ditches                 |                       |               |                          |         |
| Ditches          |                 |                         |                       |               |                          |         |

Comment: [lease road and location are snow covered](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 694901072    | 694901065   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5031122">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5031122</a> |