

Inspection Photos
Location Name: Tom L. Russell TB
Location ID: 453783



Photo 1 TB sign

Photo 2 TB

Inspection Photos
Location Name: Tom L. Russell TB
Location ID: 453783



Photo 3 dead weeds around TB.

Photo 4 dead weeds around TB area

Inspection Photos
Location Name: Tom L. Russell TB
Location ID: 453783



Photo 5 heated horiz.sep. FWKO

Photo 6 stained soil by heated horiz. Sep housing.

Inspection Photos
Location Name: Tom L. Russell TB
Location ID: 453783



Photo 7 stained soil inside FWKO housing.