

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/06/2020

Submitted Date:

01/09/2020

Document Number:

689703981

**FIELD INSPECTION FORM**

Loc ID 336048	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 4 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: 16700 Name of Operator: CHEVRON USA INC Address: 100 CHEVRON USA INC City: RANGELY State: CO Zip: 81648				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Sanford, Anita	(970) 675-3842	atlx@chevron.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295998	WELL	WO	11/17/2015	GW	045-15897	SKR 598-36-BV-01	WO
297728	WELL	WO	11/17/2015	GW	045-16929	SKR 598-36-BV-22	WO
297729	WELL	WO	11/17/2015	GW	045-16930	SKR 598-36-BV-13	WO
297730	WELL	WO	11/17/2015	GW	045-16931	SKR 598-36-BV-15	WO
297731	WELL	WO	11/17/2015	GW	045-16932	SKR 598-36-BV-17	WO
297732	WELL	WO	11/17/2015	GW	045-16933	SKR 598-36-BV-19	WO
297733	WELL	WO	11/17/2015	GW	045-16934	SKR 598-36-BV-21	WO
297734	WELL	WO	11/17/2015	GW	045-16935	SKR 598-36-BV-09	WO
297735	WELL	WO	11/17/2015	GW	045-16936	SKR 598-36-BV-11	WO
297736	WELL	WO	11/17/2015	GW	045-16937	SKR 598-36-BV-07	WO
297737	WELL	WO	11/17/2015	GW	045-16938	SKR 598-36-BV-03	WO
297738	WELL	WO	11/17/2015	GW	045-16393	SKR 598-36-BV-05	WO
297739	WELL	WO	11/17/2015	GW	045-16939	SKR 598-36-BV-20	WO
297740	WELL	WO	11/17/2015	GW	045-16940	SKR 598-36-BV-18	WO
297741	WELL	WO	11/17/2015	GW	045-16941	SKR 598-36-BV-02	WO
297742	WELL	WO	11/17/2015	GW	045-16942	SKR 598-36-BV-16	WO
297743	WELL	WO	11/17/2015	GW	045-16943	SKR 598-36-BV-12	WO
297744	WELL	WO	11/17/2015	GW	045-16944	SKR 598-36-BV-04	WO
297745	WELL	WO	11/17/2015	GW	045-16945	SKR 598-36-BV-06	WO
297793	WELL	WO	11/17/2015	GW	045-16966	SKR 598-36-BV-10	WO

297794	WELL	WO	11/17/2015	GW	045-16967	SKR 598-36-BV-08	WO
297795	WELL	WO	11/17/2015	GW	045-16968	SKR 598-36-BV-14	WO

**General Comment:**

## Follow Up Field inspection

On Monday 01/06/2020 at approximately 1200 hours, I, Inspector Mike Longworth, conducted a field inspection at CHEVRON USA SKR-65S98W 36NWSW at Location # 336048 in Garfield County, Colorado.

Not all corrective actions have been addressed from 11/18/2019 Inspection # 689703787

No emergency service number (911) and nearest road on sign.

Emergency service number (911) has been added to sign.

Nearest road not posted per corrective action.

Install sign to comply with Rule 210.b.

C.A. Date 12/19/2019

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Corrective Action: 

Date: 12/19/2019

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: <u>295998</u>	Type: <u>WELL</u>	API Number: <u>045-15897</u>	Status: <u>WO</u>	Insp. Status: <u>WO</u>
Facility ID: <u>297728</u>	Type: <u>WELL</u>	API Number: <u>045-16929</u>	Status: <u>WO</u>	Insp. Status: <u>WO</u>
Facility ID: <u>297729</u>	Type: <u>WELL</u>	API Number: <u>045-16930</u>	Status: <u>WO</u>	Insp. Status: <u>WO</u>
Facility ID: <u>297730</u>	Type: <u>WELL</u>	API Number: <u>045-16931</u>	Status: <u>WO</u>	Insp. Status: <u>WO</u>
Facility ID: <u>297731</u>	Type: <u>WELL</u>	API Number: <u>045-16932</u>	Status: <u>WO</u>	Insp. Status: <u>WO</u>
Facility ID: <u>297732</u>	Type: <u>WELL</u>	API Number: <u>045-16933</u>	Status: <u>WO</u>	Insp. Status: <u>WO</u>
Facility ID: <u>297733</u>	Type: <u>WELL</u>	API Number: <u>045-16934</u>	Status: <u>WO</u>	Insp. Status: <u>WO</u>
Facility ID: <u>297734</u>	Type: <u>WELL</u>	API Number: <u>045-16935</u>	Status: <u>WO</u>	Insp. Status: <u>WO</u>
Facility ID: <u>297735</u>	Type: <u>WELL</u>	API Number: <u>045-16936</u>	Status: <u>WO</u>	Insp. Status: <u>WO</u>
Facility ID: <u>297736</u>	Type: <u>WELL</u>	API Number: <u>045-16937</u>	Status: <u>WO</u>	Insp. Status: <u>WO</u>
Facility ID: <u>297737</u>	Type: <u>WELL</u>	API Number: <u>045-16938</u>	Status: <u>WO</u>	Insp. Status: <u>WO</u>
Facility ID: <u>297738</u>	Type: <u>WELL</u>	API Number: <u>045-16393</u>	Status: <u>WO</u>	Insp. Status: <u>WO</u>
Facility ID: <u>297739</u>	Type: <u>WELL</u>	API Number: <u>045-16939</u>	Status: <u>WO</u>	Insp. Status: <u>WO</u>
Facility ID: <u>297740</u>	Type: <u>WELL</u>	API Number: <u>045-16940</u>	Status: <u>WO</u>	Insp. Status: <u>WO</u>
Facility ID: <u>297741</u>	Type: <u>WELL</u>	API Number: <u>045-16941</u>	Status: <u>WO</u>	Insp. Status: <u>WO</u>
Facility ID: <u>297742</u>	Type: <u>WELL</u>	API Number: <u>045-16942</u>	Status: <u>WO</u>	Insp. Status: <u>WO</u>
Facility ID: <u>297743</u>	Type: <u>WELL</u>	API Number: <u>045-16943</u>	Status: <u>WO</u>	Insp. Status: <u>WO</u>
Facility ID: <u>297744</u>	Type: <u>WELL</u>	API Number: <u>045-16944</u>	Status: <u>WO</u>	Insp. Status: <u>WO</u>
Facility ID: <u>297745</u>	Type: <u>WELL</u>	API Number: <u>045-16945</u>	Status: <u>WO</u>	Insp. Status: <u>WO</u>

Facility ID:	297793	Type:	WELL	API Number:	045-16966	Status:	WO	Insp. Status:	WO
Facility ID:	297794	Type:	WELL	API Number:	045-16967	Status:	WO	Insp. Status:	WO
Facility ID:	297795	Type:	WELL	API Number:	045-16968	Status:	WO	Insp. Status:	WO

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					

Comment: [Limited BMP inspection due to snow cover.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689704000	Inspection 689703981 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5032948">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5032948</a>