

Inspection Photos

Location Name: Harrison Creek Water Treatment Facility Impound

Location ID: #425510 & Facility ID: #441238

Inspection Date: January 8, 2020



Photo #1 – View of Pond 2 looking west from Leak Detection System.



Photo #2 – View of north side of Pond 2. Note snow cover prevented liner inspection on inspection date.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Harrison Creek Water Treatment Facility Impound

Location ID: #425510 & Facility ID: #441238

Inspection Date: January 8, 2020



Photo #3 – View of Pond 3 from southeast corner.



Photo #4 – View of tank battery from southeast corner.



Inspection Photos

Location Name: Harrison Creek Water Treatment Facility Impound

Location ID: #425510 & Facility ID: #441238

Inspection Date: January 8, 2020



Photo #5 – View of east end of tank battery secondary containment. Presence of snow prevented liner inspection. No holes or tears were observed in visible portion of liner.



Photo #6 – View of west end of secondary containment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Harrison Creek Water Treatment Facility Impound

Location ID: #425510 & Facility ID: #441238

Inspection Date: January 8, 2020



Photo #7 – Overview of Pond 4 from southeast corner. Note presence of fluids on pit.



Photo #8 – Fresh Water Discharge sign has been installed in response to 4/9/2019 Field Inspection Report.

