

Inspection Photos

Location Name: LARAMIE ENERGY LLC Horseshoe Canyon /5-16 Pad

Location ID: 312630



Photo #0375 photo from entrance to location.



Photo #0376 NFPA label weathered and peeling off tank.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Horseshoe Canyon /5-16 Pad

Location ID: 312630



Photo #0377 Unmarked deadman.