

# Interim Reclamation and Stormwater Inspection

January 7, 2020

Operator: MALLARD EXPLORATION LLC- #10670

Location ID: 420020

Inspection Document #: 697501021

Weld County, CO

NWNW Section 25 T8N R62W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Cass Farms #11-25H  
Location ID: 420020



**Photo 1.** Photo taken from the entrance of location, facing South. Photo illustrates Operator sign.



Inspection Photos  
Location Name: Cass Farms #11-25H  
Location ID: 420020



**Photo 2.** Photo taken from the northern interim reclamation area, facing South. Photo illustrates location has been reduced in size only needed for production operations; however, this location does not meet Rule 1003 vegetative standards. Photo also illustrates the high density of weedy annual vegetation, Kochia, which is not reflective of reference area vegetation.

Inspection Photos  
Location Name: Cass Farms #11-25H  
Location ID: 420020



**Photo 3.** Photo taken from the northeastern interim reclamation area, facing South. Photo illustrates the high density of weedy annual vegetation, Kochia, and how that compares to the reference area vegetation. Interim reclamation area is to the right of the red-dashed line.



Inspection Photos  
Location Name: Cass Farms #11-25H  
Location ID: 420020



**Photo 4.** Photo taken from the eastern interim reclamation area, facing Southwest.  
See comments under Photo 2.