

Inspection Photos
Location Name: State Antelope 31-34-3
Location ID: 431023



Photo 1 – Pumping Unit



Photo 2 – Tank Battery

Inspection Photos
Location Name: State Antelope 31-34-3
Location ID: 431023



Photo 3 – 60 BBLS Concrete vault is missing Content and Capacity Labels



Photo 4 – Unmarked Risers

Inspection Photos
Location Name: State Antelope 31-34-3
Location ID: 431023



Photo 5 – Unmarked Risers



Photo 6 – Unmarked Risers