

**Inspection Photos**  
**Location Name: Schnieder 1-14**  
**Location ID: 320196**



**Photo#2 Production tank and Produced Water Pit**



**Photo#2 Gas Meter/Separator/Automation RTU**



Inspection Photos  
Location Name: Schnieder 1-14  
Location ID: 320196



Jan 10, 2020 at 11:15:32 AM  
N 39° 57' 45", W 104° 58' 19"  
Broomfield, CO 80023  
Adams County Oil & Gas Inspection



Jan 10, 2020 at 11:07:36 AM  
N 39° 57' 46", W 104° 58' 18"  
Broomfield, CO 80023  
Adams County Oil & Gas Inspection

Photo#3 **Corrective Action:Oil dump leaking**

Photo#4 Wellhead