

Inspection Photos
Operator: BP America
Location/API #: 067-07870
Date: 1-9-2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northwestern corner facing southward. Location is largely snow-covered at this time.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of musk thistles within the northern project area. Scattered musk thistles observed throughout the project area.



Photo 5. View of reference area, comprised of sagebrush shrubland vegetation.