

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/07/2020

Submitted Date:

01/07/2020

Document Number:

697000374

**FIELD INSPECTION FORM**

Loc ID 321574 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 61250  
Name of Operator: MULL DRILLING COMPANY INC  
Address: 1700 N WATERFRONT PKWY B#1200  
City: WICHITA State: KS Zip: 67206-

**Findings:**

17 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Akers, Tracy	719-342-1813	takers@mulldrilling.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207334	WELL	PR	02/01/2001	OW	017-06269	MULL UNIT 18	PR

**General Comment:**

[Routine Inspection](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Metal signs by tanks		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign by tanks		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Sticker on chemical drum		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Wire fence around entire location		
Corrective Action:		Date:	

<b>Equipment:</b>					corrective date
Type: LACT	# 1				
Comment:	LACT unit on north side of tank battery operated by Plains				
Corrective Action:		Date:			
Type: Emission Control Device	# 1				
Comment:					
Corrective Action:		Date:			

Type: Vertical Heater Treater	# 2	
Comment:	2-Treaters on south side of location	
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	Electric motor	
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Vertical Separator	# 1	
Comment:	Vertical gas separator in metal shed	
Corrective Action:		Date:
Type: Compressor	# 1	
Comment:	Skid mounted electric booster compressor in metal shed	
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:	Parkersburg 160	
Corrective Action:		Date:
Type: Ancillary equipment	# 6	
Comment:	Electric panel, cathodic rectifier, chemical drum w/containment, electric circ pump at battery, telemetry at LACT unit, propane tank	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	Open Top		38.847930,-102.894130
Comment:	Fiberglass open top water tank used as vent tank on west side of treaters				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		38.848360,-102.893960
Comment:	Central tank battery for (Mull Unit 15, 17, 18, 19, 20)				

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	Date:
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	Date:
Comment:	
Corrective Action:	
Date:	

**Inspected Facilities**

Facility ID: 207334 Type: WELL API Number: 017-06269 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Central tank battery for \(Mull Unit 15, 17, 18, 19, 20\)](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT