

Inspection Photos
Operator: BP America
Location/API #: 067-08983
Date: 1-9-2020



Photo 1. View of the project area from the western corner facing center.



Photo 2. View of the northwestern project area from the western corner facing northwestward. Location is snow-covered, and grasses such as crested wheatgrass and intermediate wheatgrass are observable.



Photo 3. View of the western project area from the western corner facing southward. Unused equipment stored in the southern project area.



Photo 4. View of reference area, comprised of pinyon juniper woodland.