

Investment Equipment LLC, Davis W T 1  
121-05413

Inspection #688306728

1/8/2020

Routine Inspection



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources



Colorado Oil and Gas Conservation Commission  
39.76548, -103.13061, 4694.9ft, 58°  
01/08/2020 02:03:25 PM



Colorado Oil and Gas Conservation Commission  
39.76548, -103.13061, 4691.6ft, 43°  
01/08/2020 02:03:29 PM





Colorado Oil and Gas Conservation Commission  
39.76514, -103.12944, 4694.9ft, 174°  
01/08/2020 01:58:25 PM



Colorado Oil and Gas Conservation Commission

39.65577, -102.8513, 68°

01/08/2020 01:59:22 PM



Colorado Oil and Gas Conservation Commission

39.76514, -103.12963, 4688.3ft, 264°

01/08/2020 01:59:27 PM





Colorado Oil and Gas Conservation Commission

39.76517, -103.12932, 4694.9ft, 247°

01/08/2020 01:58:08 PM



Colorado Oil and Gas Conservation Commission  
39.76516, -103.12903, 4731.0ft, 248°  
01/08/2020 01:56:50 PM





New flowline  
material.

Colorado Oil and Gas Conservation Commission  
39.76516, -103.13008, 4688.3ft, 196°  
01/08/2020 02:00:18 PM

Flowline  
material specs.

