

## Pit Status Evaluation Form

## Pit Overview:

<b>Pit Name:</b> SCHWEIZER 1	<b>Facility ID:</b> 114700
<b>Current Status:</b> Unknown	<b>Status Date:</b> 9/23/1999
<b>Current Operator:</b> TXO PRODUCTION CORP / 90735	
<b>Updated Operator:</b>	
<b>Form 15 Pit Permit Doc #:</b>	<b>Permit Date:</b>
<b>Related Facilities:</b> SCHWEIZER #1-9 (API 05-009-06224, Facility ID 205809, Loc ID 321022)	

<b>County:</b> BACA			
<b>Township:</b> 31S	<b>Range:</b> 43W	<b>Section:</b> 9	<b>QQ:</b> SWSE
<b>Original Latitude/ Longitude:</b> 37.35513 / -102.265602			
<b>Updated Latitude/ Longitude:</b> /			
<b>Basis for Location Change:</b>			

**Pit Inspection/Information Request:**

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts:	<input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

## Pit Status Evaluation:

### Pit Status Review Documents:

- |                                     |   |                |
|-------------------------------------|---|----------------|
| <input type="checkbox"/>            | Form 15 Pit Permit – Doc #:                 | Date:          |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 565491         | Date: 1/9/1990 |
|                                     | Doc #: 597148                               | Date: 2/5/1998 |
|                                     | Doc #: 689900968                            | Date: 7/9/2019 |
| <input type="checkbox"/>            | Form 27 Remediation Workplan – Project #:   | Date:          |
| <input type="checkbox"/>            | Form 4 Sundry Notice – Doc #:               | Date:          |
| <input type="checkbox"/>            | COGIS Document – Doc #:                     | Date:          |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2223928              | Date: 2/9/1998 |
| <input type="checkbox"/>            | Duplicate Record – Duplicate Pit(s) #:      |                |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) |                |
| <input type="checkbox"/>            | Other:                                      |                |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date: 9/23/1999**

#### Timing of Pit Closure:

No evidence of a pit on location. Well PA 8/31/2010, passed final inspection 7/9/2019

#### Pit Status Review Summary:

Based on records review there is no evidence that there was a pit on location; inspection reports document a fiberglass tank on location. Related well was plugged 8/31/2010 and passed final reclamation 7/9/2019. Pit status has been changed to closed.

