

Pit Status Evaluation Form

Pit Overview:

Pit Name: FRAZEE "A" 1	Facility ID: 114705
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: TXO PRODUCTION CORP / 90735	
Updated Operator:	
Form 15 Pit Permit Doc #:	Permit Date:
Related Facilities: FRAZEE A #1 (API 05-009-06255, Facility ID 205840, Loc ID 379156)	

County: BACA			
Township: 31S	Range: 43W	Section: 14	QQ: NWNW
Original Latitude/ Longitude: 37.35148 / -102.238421			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|-----------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 565502 | Date: 1/9/1990 |
| | Doc #: 590339 | Date: 3/18/1992 |
| | Doc #: 590342 | Date: 6/9/1993 |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

No evidence of a pit on location. Well PA 2/3/1993, passed final rec insp 6/9/1993

Pit Status Review Summary:

Based on records review there is no evidence that there was a pit on location; inspection reports document a fiberglass produced water tank on location. Related well was plugged 2/3/1993 and passed final inspection 6/9/1993. Pit status has been changed to closed.