

Mallard Exploration –Shoveler Pad LOC ID 455365 – Photos taken 1/13/2020 at 4:00pm



Western edge Perimeter Ditch – looking South – Berm has been compacted

Mallard Exploration –Shoveler Pad LOC ID 455365 – Photos taken 1/13/2020 at 4:00pm



Western edge Perimeter Ditch – looking North – Berm has been compacted

Mallard Exploration –Shoveler Pad LOC ID 455365 – Photos taken 1/13/2020 at 4:00pm



Northern edge Perimeter Ditch – looking Southeast – Berm has been compacted