

**Inspection Photos**  
**Operator: Logos Operating**  
**Location/API #: 067-05508**  
**Date: 1-9-2020**



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Location is snow-covered, and grasses such as western wheatgrass are observable through the snow cover.



Photo 3. View of the southern project area from the southwestern corner facing eastward. Debris identified in 2018 is no longer present.



Photo 4. View of reference area, comprised of pinyon juniper woodland.