

# *Inspection Photos*

*Loc#334232*

*Operator: Caerus*

*Inspection Number: 692401798*

*Inspection Date: 1/9/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to North and road leading out of Site to East.

January 9,2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Shideler Loc#334232



Photo#2:  
Overview of Location to South.

January 9,2020