

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/14/2020

Submitted Date:

01/14/2020

Document Number:

694901106

### FIELD INSPECTION FORM

Loc ID 334587 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                                     | Comment |
|--------------|-------|---|---------|
| , Caerus     |       | COGCC.inspections@caerus<br>oilandgas.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 277627      | WELL | PR     | 07/19/2006  | GW         | 045-10743 | GMR 33-16C (P33NWC) | PR          |
| 277629      | WELL | PR     | 09/16/2006  | GW         | 045-10742 | GMR 4-9A (P33NWC)   | PR          |
| 277630      | WELL | PR     | 10/14/2006  | GW         | 045-10741 | GMR 3-5C (P33NWC)   | PR          |
| 277635      | WELL | PR     | 10/09/2006  | GW         | 045-10740 | GMR 33-10C (P33NWC) | PR          |

**General Comment:**

COGCC Inspection Report Summary  
On Monday 1/14/20 at approximately 10:00 AM, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus P33NWC, at Location # 334587 in Garfield County, Colorado.  
While there, I observed normal production operations.  
This is a summary of inspection report.

**Location**

|                    |        |  |       |
|--------------------|--------|--|-------|
| <b>Lease Road:</b> |        |  |       |
| Type               | Access |  |       |
| comment:           |        |  |       |
| Corrective Action  |        |  | Date: |

Overall Good:

|                      |                      |  |       |
|----------------------|----------------------|--|-------|
| <b>Signs/Marker:</b> |                      |  |       |
| Type                 | BATTERY              |  |       |
| Comment:             |                      |  |       |
| Corrective Action:   |                      |  | Date: |
| Type                 | TANK LABELS/PLACARDS |  |       |
| Comment:             |                      |  |       |
| Corrective Action:   |                      |  | Date: |
| Type                 | WELLHEAD             |  |       |
| Comment:             |                      |  |       |
| Corrective Action:   |                      |  | Date: |

|                                  |     |  |             |
|----------------------------------|-----|--|-------------|
| <b>Emergency Contact Number:</b> |     |  |             |
| Comment:                         | 911 |  |             |
| Corrective Action:               |     |  | Date: _____ |

|                           |        |  |       |
|---------------------------|--------|--|-------|
| <b>Good Housekeeping:</b> |        |  |       |
| Type                      | DEBRIS |  |       |
| Comment:                  |        |  |       |
| Corrective Action:        |        |  | Date: |

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                                 |     |  |                 |
|---------------------------------|-----|--|-----------------|
| <b>Equipment:</b>               |     |  | corrective date |
| Type: Vertical Heated Separator | # 2 |  |                 |
| Comment:                        |     |  |                 |
| Corrective Action:              |     |  | Date:           |
| Type: Plunger Lift              | # 4 |  |                 |
| Comment:                        |     |  |                 |
| Corrective Action:              |     |  | Date:           |
| Type: Gas Meter Run             | # 1 |  |                 |
| Comment:                        |     |  |                 |
| Corrective Action:              |     |  | Date:           |

|                       |     |       |
|-----------------------|-----|-------|
| Type: Bird Protectors | # 1 |       |
| Comment:              |     |       |
| Corrective Action:    |     | Date: |

**Tanks and Berms:**

| Contents           | #  | Capacity | Type      | Tank ID | SE GPS |
|--------------------|--|----------|-----------|---------|--------|
| METHANOL           | 1  | 1000 GAL | STEEL AST |         | ,      |
| Comment:           | shared containment with condensate tanks |          |           |         |        |
| Corrective Action: |  |          |           |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE         | 2 | 300 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |       |
|--------------------|-------|
| Yes/No             | NO    |
| Comment:           |       |
| Corrective Action: | Date: |

**Flaring:**

|          |  |
|----------|--|
| Type     |  |
| Comment: |  |

Corrective Action:

Date:

| Inspected Facilities         |                  |       |             |             |                  |         |           |               |           |
|------------------------------|------------------|-------|-------------|-------------|------------------|---------|-----------|---------------|-----------|
| Facility ID:                 | <u>277627</u>    | Type: | <u>WELL</u> | API Number: | <u>045-10743</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| <b><u>Producing Well</u></b> |                  |       |             |             |                  |         |           |               |           |
| Comment:                     | <u>producing</u> |       |             |             |                  |         |           |               |           |
| Corrective Action:           |                  |       |             |             | Date:            |         |           |               |           |
| Facility ID:                 | <u>277629</u>    | Type: | <u>WELL</u> | API Number: | <u>045-10742</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| <b><u>Producing Well</u></b> |                  |       |             |             |                  |         |           |               |           |
| Comment:                     | <u>producing</u> |       |             |             |                  |         |           |               |           |
| Corrective Action:           |                  |       |             |             | Date:            |         |           |               |           |
| Facility ID:                 | <u>277630</u>    | Type: | <u>WELL</u> | API Number: | <u>045-10741</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| <b><u>Producing Well</u></b> |                  |       |             |             |                  |         |           |               |           |
| Comment:                     | <u>producing</u> |       |             |             |                  |         |           |               |           |
| Corrective Action:           |                  |       |             |             | Date:            |         |           |               |           |
| Facility ID:                 | <u>277635</u>    | Type: | <u>WELL</u> | API Number: | <u>045-10740</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| <b><u>Producing Well</u></b> |                  |       |             |             |                  |         |           |               |           |
| Comment:                     | <u>producing</u> |       |             |             |                  |         |           |               |           |
| Corrective Action:           |                  |       |             |             | Date:            |         |           |               |           |

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            |                 | Culverts                |                       |               |                          |         |
|                  |                 | Ditches                 |                       |               |                          |         |

Comment: [lease road and location are snow covered](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 694901115    | 694901106   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5037701">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5037701</a> |