

Inspection Photos

Loc#324264

Operator: Caerus

Inspection Number: 692401813

Inspection Date: 1/10/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to East.

January 10,2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Clem Loc#324264



Photo#2:
Overview of Location to West.

January 10,2020