

Construction and Stormwater Inspection

January 8, 2020

Operator: RED HAWK PETROLEUM LLC - #10503

Location ID: 448913

Inspection Document #: 697501023

Weld County, CO

NWNE Section 13 T2N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: L.E. Gerkin /9H
Location ID: 448913



Photo 1. Photo taken from the entrance of location, facing East. Photo illustrates Operator has not yet installed vehicle tracking device BMPs. Operator should consider installing this as one of the first BMPs.

Inspection Photos
Location Name: L.E. Gerkin /9H
Location ID: 448913



Photo 2. Photo taken from the entrance of location, facing South. Photo illustrates at the time of this inspection, there was no track out issues observed.

Inspection Photos
Location Name: L.E. Gerkin /9H
Location ID: 448913



Photo 3. Photo taken from the western perimeter of location, facing Northeast. Photo illustrates topsoil is being salvaged and stored along the western perimeter of location.

Inspection Photos
Location Name: L.E. Gerkin /9H
Location ID: 448913



Photo 4. Photo taken from the northwestern perimeter of location, facing South. Photo illustrates a temporary BMP, ditch, that has been installed around the perimeter of location.

Inspection Photos
Location Name: L.E. Gerkin /9H
Location ID: 448913



Photo 5. Photo taken from the southwestern perimeter of location, facing East. See comments under Photo 4.



Photo 6. Photo taken from the northeastern perimeter of location, facing West. See comments under Photo 4.

Inspection Photos
Location Name: L.E. Gerkin /9H
Location ID: 448913



Photo 7. Photo taken from the southern perimeter of location, facing North. Photo illustrates Operator is in-process of performing topsoil salvage operations.