

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/15/2020

Submitted Date:

01/15/2020

Document Number:

690004962

**FIELD INSPECTION FORM**

Loc ID 302872	Inspector Name: Carlile, Craig	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 21 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: 47120 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP Address: P O BOX 173779 City: DENVER State: CO Zip: 80217-				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159570	WELL	PR	01/18/2016	OW	123-40945	CHEESE 37N-28HZ	PR
159571	WELL	PR	01/26/2016	OW	123-40946	CHEESE STATE 26N-21HZ	PR
159572	WELL	PR	04/01/2019	OW	123-40947	CHEESE STATE 26C-21HZ	PR
159573	WELL	PR	07/01/2018	OW	123-40948	CHEESE STATE 1N-21HZ	PR
159574	WELL	PR	12/31/2015	OW	123-40949	CREAM STATE 28C-21HZ	PR
159575	WELL	PR	01/14/2016	OW	123-40950	CHEESE 16N-28HZ	PR
159576	WELL	PR	02/01/2018	OW	123-40951	CREAM 15N-A28HZ	PR
159580	WELL	PR	01/18/2016	OW	123-40955	CHEESE STATE 27N-21HZ	PR
159581	WELL	PR	01/26/2016	OW	123-40956	CHEESE 38N-28HZ	PR
159582	WELL	PR	01/18/2016	OW	123-40957	CHEESE 38C-28HZ	PR
159583	WELL	PR	12/29/2015	OW	123-40958	CREAM STATE 2N-21HZ	PR
159584	WELL	PR	12/28/2015	OW	123-40959	CREAM 15C-28HZ	PR
159585	WELL	PR	01/18/2016	OW	123-40960	CREAM 36N-28HZ	PR
159587	WELL	PR	01/18/2016	OW	123-40962	CREAM STATE 28N-21HZ	PR
159588	WELL	PR	12/31/2015	OW	123-40963	CREAM STATE 2C-21HZ	PR
159589	WELL	PR	12/25/2015	OW	123-40964	CREAM 37N-28HZ	PR
159590	WELL	PR	11/01/2018	OW	123-40965	CREAM 15N-B28HZ	PR
301326	WELL	SI	10/01/2017	OW	123-29959	MOSER H 28-27	SI

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Vertical Separator	# 0		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 18		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Shared battery services location number: 418028				
Corrective Action:					Date:

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:			
Corrective Action:		Date:	
<b><u>Venting:</u></b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<b><u>Flaring:</u></b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	159570	Type:	WELL	API Number:	123-40945	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	159571	Type:	WELL	API Number:	123-40946	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	159572	Type:	WELL	API Number:	123-40947	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	159573	Type:	WELL	API Number:	123-40948	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	159574	Type:	WELL	API Number:	123-40949	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	159575	Type:	WELL	API Number:	123-40950	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	159576	Type:	WELL	API Number:	123-40951	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	159580	Type:	WELL	API Number:	123-40955	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			

Facility ID:	159581	Type:	WELL	API Number:	123-40956	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	159582	Type:	WELL	API Number:	123-40957	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	159583	Type:	WELL	API Number:	123-40958	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	159584	Type:	WELL	API Number:	123-40959	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	159585	Type:	WELL	API Number:	123-40960	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	159587	Type:	WELL	API Number:	123-40962	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	159588	Type:	WELL	API Number:	123-40963	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	159589	Type:	WELL	API Number:	123-40964	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	PR								
Corrective Action:						Date:			

Facility ID:	159590	Type:	WELL	API Number:	123-40965	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [PR](#)

Corrective Action:

Date:

Facility ID:	301326	Type:	WELL	API Number:	123-29959	Status:	SI	Insp. Status:	SI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Idle Well**Purpose: ☒ Shut In☐ Temporarily Abandoned

Reminder:

Comment: [Label as plugging operations are planned.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Routine wellhead inspection.</a>	carlilec	01/15/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690004963	Photos East Side Wells	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5038591">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5038591</a>
690004964	Photos West Side Wells	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5038592">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5038592</a>