

Inspection Photos

Location Name: Nile Field Central Tank Battery

Location ID: 470860

January 14, 2020

Photo 1 – View of Tank Battery) location (storage area) from entrance (northeast of the intersection of Horrogate Rd (CR 49) and East 144th Ave. View looking west. Note equipment and materials storage including tanks.



Name: Nile Field Central Tank Battery

Location ID: 470860

January 14, 2020



Photo 2 – Location sign obscured by notices



Photo 3 – View of TB looking north. Active operations

Name: Nile Field Central Tank Battery

Location ID: 470860

January 14, 2020



Photo 3 – Looking north from TB. Note recent fence and no trespassing sign.



Photo 4 – Looking north on CR 49/lease road. Fence obstructing road access to Double bar O 2-19 (05-001-06084) and UPRR EHN 12-17 (05-001-06133).

Name: Nile Field Central Tank Battery

Location ID: 470860

January 14, 2020



Photo 5 – Chemical storage on location needs spill containment. Photo looking west.

Name: Nile Field Central Tank Battery
Location ID: 470860
January 14, 2020



Photo 6 – Minor hydrocarbon drip observed in secondary containment.



Photo 7 – Minor hydrocarbon drip observed in secondary containment..

Name: Nile Field Central Tank Battery
Location ID: 470860
January 14, 2020



Photo 8 – Pump shed.



Photo 9 – Pump shed.