

## Inspection Photos Location #334622



LOCATION



LOCATION



## Inspection Photos Location #334622



Signage is mismarked



Pumper painted over wrong operator Caerus is on the label  
on the side of tank



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos Location #334622



**Debris was found**



**Pumper removed all debris while on location**

