Inspector Name: De Paolo, Corey

FORM INSP

> Rev X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109

FIELD INSPECTION FORM





Inspection Date:
01/15/2020
Submitted Date:
01/15/2020

Document Number: 699800402

LARAMIE

LARAMIE

LARAMIE

LARAMIE

LAND&CATTLE,CO 36-11

LAND&CATTLE,CO 36-9A

LAND&CATTLE,CO. 36-7A

LAND&CATTLE,CO. 36-15

LARAMIE LAND &

CATTLE, CO 36-11A

077-09213

077-09212

077-09210

077-09209

077-09208

Loc ID	Inspector Na	me:	On-Site	Inspection		<u>Statu</u>	ıs Summary:			
334516	De Paolo, Co	orey	2/	A Doc Num:		T	THIS IS A FOLLOW UP INSPECTION			
Operator I	nformation:				FOLLOW UP INSPECTION REQUIRED					
OGCC Ope	erator Number:	10433				X	IO FOLLOW UP INSPECTION R	REQUIRED		
·	 perator: LARAMIE	FNERGY	 C			<u>Find</u>	ings:			
						17	Number of Comments			
Address: _	1401 SEVENTEEN	ITH STREI	ET #1401			0	— Number of Corrective Actions			
City:	DENVER	State:	CO	Zip: 8020)2	C	— orrective Action Response Requeste	d		
					'	P	NY CORRECTIVE ACTION(S) INTERPRETARIES INSPECTIONS THATES ADDRESSED ARE STILL	THAVE NOT		
Contact In	formation:									
Contact N	ame	Phor	ne	Email			Comment			
, Laramie				cogccnotifications@laramie- energy.com						
Kellerby, S	Shaun			shaun.kellerby	@state.co.	us				
Inspected	Facilities:									
Facility ID	Туре	Status	Status Date	Well Class	API Num		Facility Name	Insp Status		
284757	WELL	PR	09/18/2007	GW	077-0906	9	LARAMIE LAND & CATTLE CO 36-7	PR		
284758	WELL	PR	03/01/2017	GW	077-0906	57	LARAMIE LAND & CATTLE CO 36-8A	PR		
284759	WELL	PR	05/01/2010	GW	077-0906	8	LARAMIE LAND & CATTLE CO 36-8	PR		
284761	WELL	PR	12/01/2016	GW	077-0906	6	LARAMIE LAND & CATTLE CO. 36-9	PR		
284762	WELL	PR	08/18/2010	GW	077-0906	2	LARAMIE LAND & CATTLE CO 36-10A	PR		
284764	WELL	PR	07/09/2007	GW	077-0906	5	LARAMIE LAND & CATTLE 36-14A	PR		
284765	WELL	PR	02/01/2015	GW	077-0906	4	LARAMIE LAND & CATTLE CO 36-10	PR		
284767	WELL	PR	09/30/2009	GW	077-0906	3	LARAMIE LAND&CATTLE CO. 36-14	PR		

General Comment:

288275

288276

288278

288279

288280

WELL

WELL

WELL

WELL

WELL

PR

PR

PR

PR

PR

09/26/2007

03/21/2011

08/18/2010

06/24/2008

03/01/2017

GW

GW

GW

GW

GW

PR

PR

PR

PR

PR

lr	Inspector Name: De Paolo, Corey							
	COGCC Inspection Report Summary On Wednesday 1/15/20 at approximately 14:30 hours, I, Inspector Corey De Paolo, conducted an on-site inspection at LARAMIE ENERGY LLC Laramie Land & Cattle Co /36-10 Pad, Location #334516 in Mesa County Colorado. While there, I observed normal production operations. This is a summary of inspection report.							

Inspector Name: De Paolo, Corey

			Locat	<u>ion</u>			
Lease Road:							
Туре	Access						
comment:							
Corrective ActionL						Date	
Overall Good: 🔀							
Signs/Marker:							
Туре	TANK LABELS/PLACARI	os					
Comment:							
Corrective Action:						Date	:
Туре	WELLHEAD						
Comment:							
Corrective Action:						Date	:
Туре	BATTERY						
Comment:							
Corrective Action:						Date	:
Emergency Contact N	Number:						
Comment:	911						
Corrective Action:						Date	
Good Housekeeping	<u>j:</u>						
Туре	DEBRIS						
Comment:							
Corrective Action:						Date	:
Overall Good: 🔀					'		
Spills:							
Туре	Area	Volume					
In Containment: N	lo						
Comment:							
Multilple Spills a	and Releases?						
Familianiani							
Equipment:							corrective date
Type: Vertical Heated		12					
Comment:						Data	
Corrective Action:						Date:	
Type: Plunger Lift		14					
Comment:						D-4	
Corrective Action:						Date:	
Type: Bird Protectors		5					
Comment:						D :	
Corrective Action:						Date:	

Inspector Name: De Paolo, Corey # 1 Type: Pig Station Comment: Corrective Action: Date: Type: Horizontal Heated Separator #2 Comment: Corrective Action: Date: Tanks and Berms: Contents Capacity Tank ID SE GPS Type **METHANOL** 1000 GAL STEEL AST Comment: Corrective Action: Date: Paint Condition Adequate Other (Content) Other (Capacity) Other (Type) <u>Berms</u> Permeability (Wall) Permeability (Base) Maintenance Capacity Type Walls Sufficent Metal Adequate Base Sufficient Adequate Comment: Centralized containment Corrective Action: Date: SE GPS Contents Capacity Type Tank ID PRODUCED WATER 400 BBLS STEEL AST Comment: Corrective Action: Date: **Paint** Condition Adequate Other (Content) Other (Capacity) Other (Type) <u>Berms</u> Type Capacity Permeability (Wall) Permeability (Base) Maintenance Metal Adequate Walls Sufficent Base Sufficient Adequate Comment: Centralized containment Corrective Action: Date: Venting: Yes/No NO Comment: Corrective Action: Date:

spector Name: De P		
pe		
Comment:		
Corrective Action:	Date:	

nspector Na	me: De Paoi	o, corey		Inspected	d Facilities				
Facility ID:	284757	Type:	WELL	API Number:	077-09069	Status:	PR	Insp. Status:	PR
				Produc	ing Well				
C	omment: Pro	ducing							
Corrective	e Action:							Date:	
Facility ID:	284758	Type: _	WELL	API Number:	077-09067	Status:	PR	Insp. Status:	PR
	. 🗖			Produc	ing Well				
	omment: Pro	oducing						5.	
Corrective	e Action:							Date:	
Facility ID:	284759	Type:	WELL	API Number:	077-09068	Status:	PR	Insp. Status:	PR
	201700	<u> </u>	***************************************		ing Well				110
C	omment: Pro	oducina		110000	<u>gטוו</u>				
Corrective								Date:	
Facility ID:	284761	Type:	WELL	API Number:	077-09066	Status:	PR	Insp. Status:	PR
				Produc	ing Well				
C	omment: Pro	ducing							
Corrective	e Action:							Date:	
Facility ID:	284762		WELL	API Number:	077-09062	Status: _	PR	Insp. Status:	PR
	. 5			<u>Produc</u>	ing Well				
	omment: Pro	ducing						D. (c)	
Corrective	e Action:							Date:	
Facility ID:	284764	Type:	WELL	API Number:	077-09065	Status:	PR	Insp. Status:	PR
					ing Well				
C	omment: Pro	ducing							
Corrective	e Action:							Date:	
Facility ID:	284765	Type: _	WELL	API Number:	077-09064	Status:	PR	Insp. Status:	PR
				Produc	ing Well				
C	omment: Pro	ducing							
Correctiv	e Action:							Date:	
Facility ID:	284767	Type:	WELL	API Number:	077-09063	Status:	PR	Insp. Status:	PR
acility ID	204/0/	Type: _	VVELL			Status	rr -	irisp. status	rĸ
C	omment: Pro	nducing		PIOUUC	ing Well				
Corrective								Date:	
231100117								Date.	

Inspector Na	me: De Pa	olo, Corey							
Facility ID:	288275	Type: _	WELL	API Number:	077-09213	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
C	omment: P	roducing							
Corrective	e Action:							Date:	
Facility ID: _	288276	Type: _	WELL	API Number:	077-09212	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
C	omment: P	roducing							
Corrective	e Action:							Date:	
Facility ID: _	288278	Type: _	WELL	API Number:	077-09210	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
C	omment: P	roducing							
Corrective	e Action:							Date:	
	•								
Facility ID: _	288279	Type: _	WELL	API Number:	077-09209	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
C	omment: P	roducing							
Corrective	e Action:							Date:	
	·								
Facility ID: _	288280	Type: _	WELL	API Number:	077-09208	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
C	omment: P	roducing							
Corrective	e Action:							Date:	

	Reclamation - Storm Water - Pit								
Storm Water:									
oc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment			
Berms									
Ditches									
		Ditches							
		Compaction							
Compaction									
		Gravel							
		Culverts							
Gravel									
Commen	:					7			
Corrective Action						Date:			
Pits: 👿 NO	SURFACE INDI	CATION OF PIT							
Attached Docun	<u>nents</u>								
ou can go to CC	OGCC Images (https://cogcc.state.co	.us/weblink/) ar	nd search by doc	ument number:				
Document Num	Description	URL							
	Photos for Insp #699800402	http://ogo	cweblink.state.co	.us/DownloadDocu	umentPDF.aspx?	DocumentId=5039049			

Date Run: 1/15/2020 Doc [#699800402]