

Inspection Photos
Location Name: Blehm 19-L Pad
Location ID: 433645




Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos
Location Name: Blehm 19-L Pad
Location ID: 433645



Colorado Oil and Gas Conservation Commission
40.55743, -104.9287, 1502.2m, 31°
Jan 16, 2020 14:40:07

Photo 3: Stained soil



Colorado Oil and Gas Conservation Commission
40.55742, -104.92873, 1500.4m, 357°
Jan 16, 2020 14:40:25

Photo 4: Wellhead Sign

Inspection Photos
Location Name: Blehm 19-L Pad
Location ID: 433645



Photo 5: Wellhead




Photo 6: Stained soil