

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/16/2020

Submitted Date:

01/16/2020

Document Number:

699100924

FIELD INSPECTION FORM
 Loc ID 322938 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244496	WELL	TA	04/12/2019	GW	123-12291	KOHLER 6-21	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action: _____ Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 244496 Type: WELL API Number: 123-12291 Status: TA Insp. Status: TA**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: T/A, has red "PTA" variance tag waiting on the cut and cap crew.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 1/16/20 at approximately 1050 hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Kohler 6-21 of Noble Energy at API # 05-123-12291 in Weld County, Colorado.</p> <p>While there, I observed a Production well that is T/A, has red "PTA" variance tag waiting on the cut and cap crew.</p> <p>No violation of the COGCC rules were observed at the time of inspection.</p> <p>This is a summary of inspection report.</p> <p>Continuing education inspections</p>	burnsa	01/16/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699100925	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5040542